

## BOAT SPECIFICATION

Vitals			
<b>Boat Name:</b>	Wild Thyme	<b>Index No:</b>	74042
<b>Build Year:</b>	1987	<b>Stern:</b>	Cruiser
<b>Length:</b>	36'	<b>Beam:</b>	Narrow beam (6'10)
Configuration			
<b>Boat Builder:</b>	Stowe Hill Marine	<b>Fit Out / Layout:</b>	Professional / Mid Reverse
<b>Specification:</b>	Steel	<b>Hull Type:</b>	Flat
<b>Cabin Height:</b>	6'6 <i>Approximately</i>	<b>Berths:</b>	Single
Propulsion			
<b>Engine:</b>	Vetus Diesel	<b>Cylinders:</b>	3
<b>Cooling:</b>	Keel	<b>Gearbox:</b>	PRM
<b>Diesel Tank Capacity:</b>	TBC	<b>Last Service:</b>	April 2024
Heating & Water			
<b>Central Heating:</b>	X	<b>Stove:</b>	Boatman Solid Fuel Stove
<b>Calorifier:</b>	X	<b>Water Boiler:</b>	Morco Water Boiler
<b>Immersion:</b>	X	<b>Water Tank &amp; Capacity:</b>	TBC
Electrical			
<b>12v Lighting:</b>	✓	<b>12v Power:</b>	✓
<b>240v Landline:</b>	X	<b>Inverter:</b>	2000W Power Inverter (Streetwize)
<b>Solar Panels:</b>	X	<b>Generator:</b>	X
<b>Batteries:</b>	X2 Domestic Lead Acid x1 Starter	<b>Additional Systems:</b>	
Bathroom Specification			
<b>Toilet Type:</b>	Porta Potti WC	<b>Shower:</b>	✓
<b>Bath:</b>	X	<b>Vanity Basin:</b>	✓
Galley Specification			
<b>Fridge:</b>	12V Mini under counter	<b>Oven &amp; Hob:</b>	✓
<b>Freezer:</b>	X	<b>Microwave:</b>	X
Fit Out Specifics			
<b>Insulation:</b>	Polystyrene	<b>Type of Wood:</b>	Hardwood Oak T&G
<b>Windows:</b>	Single Glazed	<b>Exterior Doors:</b>	X2
<b>Side Hatch:</b>	X		
Boat History			
<b>BSSC Expiry:</b>	Until 2028	<b>Last Blacked:</b>	May 2023
<b>Last Survey:</b>	May 2023 (See below)	<b>Anodes Fitted:</b>	New from May 2023 x4
<b>Builders Plaque:</b>	✓	<b>HIN:</b>	031C987
<b>Owner's Manual:</b>	✓	<b>Engine Paperwork:</b>	X
<b>Additional Notes:</b>	The last survey was conducted for the vendor before brokerage last year in 2023. It was on inspection that the base plate was found to be in places as low as 5.7mm. Considering the baseplate was originally 6mm from 1987, it is considered to have aged well. However, in the surveyor's opinion, it needed over plating. A full over plate of the base plate was done with an additional 5mm plate. There are receipts for all this work and evidence of this being undertaken at Keel Services.		

Whilst every effort is applied to describe a boat accurately, as some of the information is provided by the vendor

Boat Sales & More will not accept any responsibility for a description that is not 100% accurate.